

Inspection Photos
Location Name: Federal Land Bank 21-14
Location ID: 313164



Photo 1. Overview of location taken facing southwest.



Photo 2. Example of sediment migration on access road.

