

Inspection Photos
Location Name: Federal Land Park 33-15
Location ID: 313163



Photo 1. Overview of location taken facing west.



Photo 2. Annual weeds on location.

Inspection Photos
Location Name: Federal Land Park 33-15
Location ID: 313163



Photo 3. Unmarked risers.



Photo 4. Example of sediment migration on access road.

