

Inspection Photos

7/1/2020

Operator: OXY USA WTP LP - 66571

Location ID: 323892

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OXY USA WTP LP - 66571

Location ID: 323892



Photo 1: Photo taken from the south end of the Location, facing north. Photo shows areas on the south end of the Location where uniform vegetative establishment has not been achieved. Livestock grazing pressure evident and may be hindering reclamation.



Photo 2: Photo taken from the west end of the Location, facing south. Photo shows example of areas where perimeter fence is in disrepair.

Inspection Photos

Operator Name: OXY USA WTP LP - 66571

Location ID: 323892



Photo 3: Photo taken from the north end of the Location, facing west. Photo shows reclamation on the north end of the Location appears to have achieved uniform vegetative establishment.



Photo 4: Photo taken from the south end of the Location. Photo shows Field Bindweed has established on the Location. This is a Colorado State listed noxious weed and needs to be managed.

Inspection Photos
Operator Name: OXY USA WTP LP - 66571
Location ID: 323892



Photo 10: USGS Aerial Imagery Dated 9/2/1980. Well was SPUD 4/4/1980. Photo shows the disturbance area of this Location ~ 5 months post drilling activities.

