

Inspection Photos
Location Name: Bulldog 22-41V-890
Location ID: 433805



Photo 1. Overview of location taken facing south. Annual weeds on location.



Photo 2. Noxious weeds on location.



Inspection Photos
Location Name: Bulldog 22-41V-890
Location ID: 433805



Photo 3. No interim reclamation apparent.



Photo 4. No interim reclamation apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources