

Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 1. Overview of location taken facing west.



Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 2. Separator stored on location.



Photo 3. Noxious weeds on location.

