

# Final Reclamation and Stormwater Inspection

June 30, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320314

Inspection Document #: 697501695

Adams County, CO

SESE Section 13 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 1.** Photo taken from the entrance of location, facing West. Photo illustrates final reclamation activities have been performed with the evidence of straw crimped mulch and drill rows. However, very little germination was observed throughout the disturbance area. Some of the reference area plant species consisted of smooth brome and western wheatgrass.

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 2.** Photo taken from the entrance of location, facing North. Photo illustrates a culvert that has not been removed. Operator may need to remove that culvert or provide surface owner documentation.

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 3.** Photo taken from the eastern access road, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 4.** Photo taken from the southern well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 5.** Photo taken from the southern well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 6.** Photo taken from the associated offsite tank battery location, facing West. See comments under Photo 1.