

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Ed Koch /7-9 Pad

Location ID: 312638



Photo #1450 from entrance to location



Photo #1028 from inspection #699800972 inspection conducted on 4/23/20.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Ed Koch /7-9 Pad

Location ID: 312638



**Photo #1451 Secondary containment berm has eroded.**