

# *Inspection Photos*

*Loc#322432*

*Operator: Terra*

*Inspection Number: 692402336*

*Inspection Date: 6/23/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location and East side Interim which appears hard packed and populated with ruderal, debris weeds.

June 23, 2020



Photo#2:

West side Interim area.

June 23, 2020