

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #1 Wells & Signs



Photo #2 Heater Treaters

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #3 Unused Stainless lines



Photo #4 Maintenance Vault

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #5 Test Buildings



Photo #6 Gaslift

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #7 Unused Methanol Tote




Photo #8 Unused Methanol Tote

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #9 Missing/Faded Placards



Photo #10 Unused Equipment

Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #11 Location



Photo #12 Gas Meter Runs



Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #13 Missing sign/placard for pits



Photo #14 Missing sign/placard for pits



Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #15 Missing sign/placard for pits



Photo #16 Missing sign/placard for pits



Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #17 Trash



Photo #18 Trash



Inspection Photos
Location Name: Latham 34-2 Pad
Location ID: 432800



Photo #19 Unused Equipment



Photo #20 Unused Equipment

