

Inspection Photos
Location Name: VALLEJO 44-5V
API#: 05-071-08844
INSP. #: 695102930



Colorado Oil & Gas Conservation Commission
37.19445, -104.90601, 2276.0m, 74°
2020/06/30 15:11:44

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.01473, -104.49136, 356°
2020/06/30 15:09:02

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: VALLEJO 44-5V
API#: 05-071-08844
INSP. #: 695102930



**PHOTO 3: SOUND METER SET 350' TO THE WEST BETWEEN
LOCATION AND COMPLAINTANTS HOUSE.**