

Inspection Photos

Location Name: LARAMIE ENERGY LLC Buzzard Creek /14B Pad

Location ID: 334555



Photo #1454 from entrance to location



Photo #1455 Multiple holes in tank containment liner.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Buzzard Creek /14B Pad

Location ID: 334555



Photo #1456 Multiple holes in tank containment liner.