

BP L48 San Juan



## V2 Compliance Follow Up Form

18145544066

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20200617-18145544066

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jun 17, 2020 7:47:59 AM MDT

557 Airpark Dr, Durango, CO 81303, USA

Jun 17, 2020 7:47:50 AM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

**Name**

colen@horizonenvservices.com

**Date**

Jun 15, 2020

**Well Name**

FEDERAL LAND BANK GAS UNIT D 2

**API Number**

50670826200

**Select State**

Colorado

**Work type**

COGCC Inspection AR

**Action Complete**

Other

**Photo of first corrective action completed**



Completed work description Corrective  
Action 1

location sign

Photo of second corrective action completed





**Completed work description of corrective action 2**

treated Russian knapweed and musk thistle

**Photo of third corrective action completed**





**Completed work description of corrective  
action 3**

treated noxious weeds

**Photo of fourth corrective action completed**





**Completed work description**

treated noxious weeds on roadsides

**Completed work description of corrective action 4**

treated noxious weeds in reclamation area and on road

**Additional photos**

**Completed work description**

treated noxious weeds in reclamation area and on road

**Summary of all work completed**

previous treatment dates 7/8/16, 6/28/17, 6/20/18, 5/7/19