

BP L48 San Juan



V2 Compliance Follow Up Form

18145544274

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200617-18145544274

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jun 17, 2020 7:54:50 AM MDT

557 Airpark Dr, Durango, CO 81303, USA

Jun 17, 2020 7:57:34 AM MDT [[View Map](#)]

INFORMATION

Section 1

| | |
|---|--------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Jun 15, 2020 |
| Well Name | FEDERAL LAND BANK GAS UNIT D 1 |
| API Number | 50670681900 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Other |
| Photo of first corrective action completed | |



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

treated noxious weeds

Photo of third corrective action completed



**Completed work description of corrective
action 3**

treated noxious weeds

Photo of fourth corrective action completed



Completed work description

treated noxious weeds on road

Completed work description of corrective action 4

treated noxious weeds in reclamation area and on road

Additional photos

**Completed work description**

treated noxious weeds in reclamation area and on road

Summary of all work completed

previous treatment dates 7/8/16, 6/28/17, 6/20/18, 5/7/19