

Inspection Photo

ALs Loc#419862

Operator: Terra

Inspection Number: 692402191

Inspection Date: 5/14/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Unused equipment on location: flowlines & Risers.

May 14, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead ALs Loc#419862