

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Bradenhead	# 1	

Comment: Appears to be plumbed to surface.		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment: one is not in service		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		
Comment: Shares containment with crude oil tank.					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	48 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		40.264730,-104.466600
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 239904 Type: WELL API Number: 123-07692 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 7/7/20 at approximately 1141hrs, I, Inspector Adam Burns, Conducted an on-site inspection at State 25 of Noble Energy at Location ID: 317745 in Weld County, Colorado. While there, I observed a production well that is producing. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report. Continuing education inspections</p>	burnsa	07/07/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102030	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191411