

Inspection Photos

API: 071-09685

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 1. Facing south toward the pre-existing access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 2. Facing west. Sediment traps are installed along the road to capture stormwater runoff from the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 3. Facing west along the pre-existing access road. There are water bars installed along the road to divert stormwater off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 4. Facing southeast at the beginning of the access road which has been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 5. Facing southeast along the reclaimed access road. Perennial vegetation has uniformly established along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 6. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 7. Facing east toward the location. Vegetation has uniformly established at the location and consists of Orchard grass, Western wheat grass, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 8. Facing east at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 9. Facing northwest at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 10. Facing west at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 11. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020

Inspection Photos



Photo 12. Facing west toward undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09685 | Date: 7/6/2020