

Inspection Photos

API: 071-08738

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 1. Facing northwest near the beginning of the access road. The road remains per approved variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 2. The culverts along the access road have been cleaned out and repaired..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 3. Further along the access road. The road is stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 4. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 5. The culvert near the location has been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 6. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 7. Facing east along the fill slope. Vegetation is well established along fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 8. Facing toward the cut slope which appears to be stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 9. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020

Inspection Photos



Photo 10. Facing back southwest along the access road. Vegetation is well established along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 7/6/2020