


# Inspection Photos

Location Name: MV 29-27

Location ID: 323789 & Spill/Release Document: 2148673

Inspection Date: June 23, 2020



Location sign



Tank battery



## Inspection Photos

Location Name: MV 29-27

Location ID: 323789 & Spill/Release Document: 2148673

Inspection Date: June 23, 2020



Replaced condensate tank



Tank battery secondary containment structure



## Inspection Photos

Location Name: MV 29-27

Location ID: 323789 & Spill/Release Document: 2148673

Inspection Date: June 23, 2020



Tank battery secondary containment structure, note metal support directly on secondary containment liner



Tank battery secondary containment structure

