

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2020

Submitted Date:

07/07/2020

Document Number:

699700168**FIELD INSPECTION FORM**Loc ID 323789 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

General Comment:

On June 23, 2020, COGCC Staff John Heil conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 323789 MV 29-27 and Spill/Release Form 19/19A Doc #2148673.

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: 66

Comment: 4/13/2014 TEP (Formally WPX) submitted a Form 19 when a small hole in a condensate tank released 66 bbl of fluids into the secondary containment structure. It was reported that a vac truck was able to recover 100% of the fluids and there were no impacts outside of secondary containment. See SPILL/RELEASE REPORT Doc #2148673 for more information. 6/23/2020 J.Heil conducted an inspection in and around the tank battery where the spill/release occurred. There were no impacts in or around the tank battery and the secondary containment structure was intact with no tears or holes at time of inspection.

Corrective Action: Operator shall provide the status and update of Spill/Release Form 19/19A Doc #2148673 on a eForm 4 Sundry.

Date: 09/07/2020

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700169	20200623 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191794