

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06954**  
**Date: 7/6/2020**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with grasses such as Indian ricegrass and forbs such as *Heterotheca villosa*.



Photo 3. View of the southwestern fill slope facing eastward.



Photo 4. View of the reference area, comprised of pinyon and juniper woodland with gembel oak and a mix of native and forbs such as blue grama, Sandberg bluegrass, and Navajo tea.