

Final Reclamation Inspection

July 8, 2020

Operator: APOLLO OPERATING LLC - #10051

API #: 05-121-11052

Inspection Document #: 697501718

Washington County, CO

SWSW Section 31 T4S R51W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rodwell #14-31
API #: 05-121-11052



Photo 1. Photo taken from the approximate central location, facing West. Photo illustrates a wheat field that has been recently harvested. The establishment of wheat was consistent and reflective throughout reference crop areas.

Inspection Photos
Location Name: Rodwell #14-31
API #: 05-121-11052



Photo 2. Photo taken from the approximate central location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Rodwell #14-31
API #: 05-121-11052



Photo 3. Photo taken from the approximate central location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Rodwell #14-31
API #: 05-121-11052



Photo 4. Photo taken from the approximate central location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Rodwell #14-31
API #: 05-121-11052



Photo 5. Photo taken from the eastern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Rodwell #14-31
API #: 05-121-11052



Photo 6. Reference photo taken northeast of the location, facing West. See comments under Photo 1.