

Inspection Photos
Location Name: FOE-66N64W /20NWSE
Location #: 331521



Photo #1

Foe 33-20 (05-123-20827) Wellsite
Plugged & Abandoned | PA
~ 180 yds.



Photo #2

Foe 33-20 Battery site
Abandoned: ALL Equipment Removed