

## Inspection Photos

Location Name: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY WOLF CREEK UNIT-  
GOVT-69S90W /1SWNE

Location ID: 314165



Photo #1484 from entrance to location



Photo #1485 Tank missing required information.

## Inspection Photos

Location Name: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY WOLF CREEK UNIT-  
GOVT-69S90W /1SWNE

Location ID: 314165



Photo #1486 Tank label weathered and not legible.



Photo # 1487 Trash on location.

## Inspection Photos

Location Name: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY WOLF CREEK UNIT-  
GOVT-69S90W /1SWNE

Location ID: 314165



**Photo #1488 Multiple places with stained soils outside of containment.**



**Photo #1489 Multiple places with stained soils outside of containment.**