

Inspection Photos

API: 055-06301

Operator: TABULA RASA ENERGY

Inspection Date: 7/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06301 | Date: 7/8/2020

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/8/2020

Inspection Photos



Photo 2. Well sign has been updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/8/2020

Inspection Photos



Photo 3. The unused equipment previously observed has been removed. Corrective action completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/8/2020