

# Inspection Photos

API: 055-06209

Operator: TABULA RASA ENERGY

Inspection Date: 7/9/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 7/9/2020

## Inspection Photos



**Photo 1.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 7/9/2020

## Inspection Photos



**Photo 2.** Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 7/9/2020