

Inspection Photos
Location Name: RGU 23-6-297
Location ID: 335602 & Spill/Release ID: 477183
Inspection Date: July 9, 2020



Location sign



Location sign



Inspection Photos

Location Name: RGU 23-6-297

Location ID: 335602 & Spill/Release ID: 477183

Inspection Date: July 9, 2020



View of the location from County Road 24



Pump house, facility lease road and erosion rills that were potentially created by the spill/release



Inspection Photos

Location Name: RGU 23-6-297

Location ID: 335602 & Spill/Release ID: 477183

Inspection Date: July 9, 2020



Erosion rills potentially created by the spill/release



Erosion rills leading to the area where the fluids appeared to have pooled



Inspection Photos

Location Name: RGU 23-6-297

Location ID: 335602 & Spill/Release ID: 477183

Inspection Date: July 9, 2020



Potentially impacted (stained) material (red circle)



Mud cracks where the fluids appeared to have pooled



Inspection Photos

Location Name: RGU 23-6-297

Location ID: 335602 & Spill/Release ID: 477183

Inspection Date: July 9, 2020



Mud cracks and moist soil where the fluids appeared to have pooled



Mud cracks and moist soil located west of the pump house