

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2020

Submitted Date:

07/10/2020

Document Number:

699700171

FIELD INSPECTION FORM

Loc ID 335602 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

General Comment:

On July 9, 2020, COGCC Staff John Heil conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 335602 Federal 23-6-297 and Spill/Release ID 477183.

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: 7/7/2020 A corroded carbon steel bushing located within the pump house spilled/released produced water. The produced water traveled south over the facility lease road and pooled in a shallow depression. See Form 19 Doc #402439440 Spill/Release ID 477183 for more information. 7/9/2020 Erosion rills were present on the south side of the facility access road. Beyond the access road was an area with mud cracks where the spilled/released fluids appeared to have pooled. Potential impacted material (stained soil) was observed in the area where the fluids had pooled. A detectable hydrocarbon odor was present at time of inspection.

Corrective Action: Properly dispose of oily waste in accordance with 907.e. Date: 07/25/2020

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700173	20200709 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5194161