

Inspection Photos  
Location Name: Riteaway NW-32 Pad  
Location ID: 322682



Photo 1: Wellhead Sign



Photo 2: Wellhead; UNUSED/DISCONNECTED EQUIPMENT

Inspection Photos  
Location Name: Riteaway NW-32 Pad  
Location ID: 322682




Photo 3: Wellhead Sign




Photo 4: Weeds

Inspection Photos  
Location Name: Riteaway NW-32 Pad  
Location ID: 322682



Colorado Oil and Gas Conservation Commission  
40.36268, -104.92013, 1444.6m, 294°  
Jul 10, 2020 12:16:00

Photo 5: Wellhead Sign



Colorado Oil and Gas Conservation Commission  
40.36268, -104.92015, 1444.8m, 210°  
Jul 10, 2020 12:16:05

Photo 6: Weeds

Inspection Photos  
Location Name: Riteaway NW-32 Pad  
Location ID: 322682




Photo 7: Wellhead Sign



Photo 8: Weeds

**Inspection Photos**  
**Location Name: Riteaway NW-32 Pad**  
**Location ID: 322682**



**Photo 9: Tank Battery**