

Inspection Photos

6/24/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312445

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 1: Photo shows the southwest corner of the Location, facing north. Photos 1-3 provide an overview of the Location from North, to east, to southeast. Photo shows unused equipment, or equipment not needed for production remains stored on the Location and interim areas. Photos also show (with exception to the plugging and removal of surface production equipment), no interim or final reclamation activities have been conducted on the Location.

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the south end of the Location, facing west. Photos 4-8 provide an overview of the Location from west, northwest, northeast to east. See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 5: See comments under photo 4 and 1.



Photo 6: See comments under photo 4 and 1

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 7: See comments under photo 4 and 1



Photo 8: Photo taken from the northeastern area of the Location. Photo shows area where the former tank battery was located.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 9: Photo taken from the eastern areas of the Location, facing east. Photo shows unused equipment, or equipment not needed for production remains stored on the Location and interim areas. Photos also show (with exception to the plugging and removal of surface production equipment), no interim or final reclamation activities have been conducted on the Location



Photo 10: Photo taken from the northwestern area of the Location. See comments under photo 9.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 10: USGS Aerial Imagery Dated 9/2/1980. Well was SPUD 4/4/1980. Photo shows the disturbance area of this Location ~ 5 months post drilling activities.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 11: 8/1993 Google Earth aerial image. Photo shows disturbance area of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 12: 6/2016 Google Earth aerial image. Most recent available Google Earth Imagery. Photo shows disturbance area of the Location subject to final reclamation requirements. Surface Owner appears to have disturbed areas north and northwest of the Location.