

Inspection Photos
Operator: Kinder Morgan
API: 083-06574
Date: 7/9/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern project area facing westward. Revegetation is progressing with crested wheatgrass, and western wheatgrass, rubber rabbitbrush, and fourwing saltbush.



Photo 3. View of the western project area facing northward. Scattered Russian knapweeds observed throughout the project area. Approximately 2000 individuals observed.




Photo 4. Another view of Russian knapweeds within the project area.



Photo 5. View of the reference area, comprised of pinyon juniper woodland with sagebrush understory and grasses/forbs such as Indian ricegrass, snakeweed, and penstemon.