

Inspection Photos

Operator: Kinder Morgan
API: 083-06339
Date: 7/9/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of area in the northern project area where revegetation is recently conducted. Hay mulch and young grasses observed within the revegetation areas.



Photo 3. Birdseye view of hay mulch and young grass seedlings in the northern project area.




Photo 4. View of dense Russian knapweeds within the northern project area. Approximately 2000 individuals observed.



Photo 5. View of the northern project area from the norwestern corner facing eastward. Revegetation is progressing in portions with grasses such as crested wheatgrass and shrubs such as fourwing saltbush and rubber rabbitbrush.



Photo 6. View of the reference area, comprised of pinyon juniper woodland with sagebrush understory and grasses/forbs such as Indian ricegrass, snakeweed, and penstemon.