

Inspection Photos
Operator: Kinder Morgan
API: 083-06593
Date: 7/9/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area facing eastward from the southwestern corner. Vegetation is within a dryland wheat field in a mowed condition.



Photo 3. View of the northern project area facing eastward from the northwestern corner. Revegetation is progressing with grasses such as crested wheatgrass as well as shrubby rubber rabbitbrush.



Photo 4. View of staining approximately 3 feet in diameter, within the northwestern portion of the well pad.



Photo 5/6. View of the reference area, comprised of both dryland wheat field, and pinyon juniper woodland with sagebrush understory and grasses/forbs such as Indian ricegrass, snakeweed, and penstemon.