

BP L48 San Juan



V2 Compliance Follow Up Form

18146359648

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200624-18146359648

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Jun 24, 2020 1:45:21 PM MDT

1256 Co Rd 510, Durango, CO 81303, USA

Jun 24, 2020 1:41:12 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Jun 12, 2020
Well Name	ANNALA FEDERAL GAS UNIT A 1
API Number	50670774100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils
Photo of first corrective action completed	



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Built diversion ditch

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Fixed erosion

Photo of fourth corrective action completed



Completed work description

Cleaned up stains

Completed work description of corrective action 4

Built rock run downs

Additional photos



Additional photos



Additional photos

**Summary of all work completed**

Compliance , cleaned up trash , installed rock run down built diversion ditch and cleaned up stains