

BP L48 San Juan



V2 Compliance Follow Up Form

18147507594

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200707-18147507594

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Jul 7, 2020 10:13:14 AM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Jul 7, 2020 10:16:29 AM MDT [[View Map](#)]

INFORMATION

Section 1

| | |
|---|------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Jul 6, 2020 |
| Well Name | KLUSMAN GAS UNIT 33-34 2 |
| Location Name (Other) | klusman gu 33-34 4 |
| API Number | 50670876400 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Other |
| Photo of first corrective action completed | |



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

view of location

Photo of third corrective action completed



Completed work description of corrective action 3

treated noxious weeds in reclamation area

Photo of fourth corrective action completed



Completed work description

view of location

Completed work description of corrective action 4

treated noxious weeds on location and entrance road

Additional photos

**Completed work description**

treated noxious weeds in reclamation area and on entrance road

Summary of all work completed

previous treatment dates were 7/19/16, 7/7/17, 6/26/18, 7/1/19