

BP L48 San Juan



V2 Compliance Follow Up Form

18146347120

Reference Number:

20200624-18146347120

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Submission Date:

Jun 24, 2020 11:27:05 AM MDT

Location:

557 Airpark Dr, Durango, CO 81303, USA

Jun 24, 2020 11:26:47 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jun 23, 2020

Well Name

BROWN GAS UNIT 32-6-03 1

API Number

50670762000

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

removed weed debris

Photo of third corrective action completed



**Completed work description of corrective
action 3**

removed weed debris

**Completed work description of corrective
action 4**

removed weed debris and recent treated musk
thistles

Completed work description

removed weed debris from around the pad.
walked the pad for trash and other debris.
remixed recent treated thistle.

Summary of all work completed

.