

Inspection Photos

7/8/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 391243

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 391243



Photo 1: Photo taken from the north end of the Location, facing southeast. Photo shows additional reclamation activities and weed management does not appear to have been conducted.



Photo 2: Photo taken from the north end of the Location, facing southwest. Photo shows additional reclamation activities and weed management does not appear to have been conducted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 391243



Photo 3: Photo of the Location. Photo shows what appears to be Musk thistle and field bindweed. These are Colorado State listed noxious weeds.