

Inspection Photos

7/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312473

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312473



Photo 1: Photo taken from the south end of the Location, facing Northwest. Photo shows Location has not been reclaimed; Various pipe and debris appears to be stored on the Location. Gravel has not been removed; Compaction alleviation, recontouring/regrading and revegetation activities have not been conducted.



Photo 2: Photo taken from the south end of the Location, facing Northeast. See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312473



Photo 3: Photo of pipe stored on the west end of the Location.

Photo 4: Photo taken from the east end of the Location, facing southwest. Photo shows Location has not been reclaimed in accordance with 1004 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312473



Photo 5: Photo taken from the east end of the Location, facing northwest. Photo shows Location has not been reclaimed in accordance with 1004 rules. Photo also shows various debris stored on the north end of the Location.



Photo 6: Photo taken from the east end of the Location, facing north. Photo shows Location has not been reclaimed in accordance with 1004 rules.