

Inspection Photos

7/8/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312455

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312455



Photo 1: Photo taken from the southwest end of the Location facing north. Photo shows reclamation of the Location is not progressing toward COGCC 1004 standards; Vegetation seen in photo noxious weeds consisting of Field Bindweed or Houndstongue. Little to no desirable perennial vegetative establishment observed on Location.



Photo 2: Photo taken from the southwest end of the Location facing east. See comments under photo 1.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312455



Photo 3: Photo of vegetation on Location; Vegetation observed on Location predominantly Field Bindweed or Houndstongue. Little to no desirable perennial vegetative establishment observed on Location.



Photo 4: See comment under photo 3. .