

Inspection Photos  
Location Name: Cummings 19-23  
Location ID: 302236



Photo 1: Wellhead Sign



Photo 2: Wellhead; Overgrown weeds

