

Inspection Photos
Location Name: FOOSE-66N64W /18NWSE
Location #: 326915



Photo #1
Foose A18-10 (05-123-13855) Wellsite
Plugged & Abandoned | PA
~ 5 yds.
Reclamation progressing



Photo #2
Foose A18-23, A18-9 Battery site
Inactive | Shut-down
Formerly served:
Foose A18-10
Plugged & Abandoned | PA