

Final Reclamation Inspection

July 13, 2020

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 445738

Inspection Document #: 697501756

Weld County, CO

NWNW Section 30 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bears 4-30 and 5-30 Tank
Battery
Location ID: 445738



Photo 1. Photo taken from the western tank battery location, facing East. Photo illustrates Operator has removed all equipment. Unmanaged Kochia and Russian thistle weeds were observed. Also, there was no to very little establishment of desirable vegetation.

Inspection Photos
Location Name: Bears 4-30 and 5-30 Tank
Battery
Location ID: 445738



Photo 2. Photo taken from the south central tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Bears 4-30 and 5-30 Tank
Battery
Location ID: 445738



Photo 3. Reference photo taken from the tank battery location, facing South.