

Inspection Photos

7/14/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335618

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335618



Photo 1: Photo taken from the south end of the Location, facing west. Photo shows transport/storage of surface cuttings on the Location does not appear to have commenced.



Photo 2: Photo taken from the south end of the Location, facing east. Photo shows soil salvage, or transport/storage of surface cuttings on the Location does not appear to have commenced.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335618



Photo 3: Photo taken from the interim areas. Photo shows Musk thistle remnants from previous weed management activities.



Photo 4: Photo taken from the interim areas. Photo shows viable Musk thistle plants remain on the interim areas.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335618



Photo 5: Photo taken from the interim areas. Photo shows viable Musk thistle plants remain on the interim areas.



Photo 6: Photo taken from the interim areas. Photo shows viable Musk thistle plants remain on the interim areas.