

Inspection Photos  
Location Name: Shively #21-12  
Location ID: 320049



Photo #1 Tanks.

Photo #2 Meter.

Inspection Photos  
Location Name: Shively #21-12  
Location ID: 320049



**Photo #3 Separator & Heater treater.**

**Photo #4 ECD.**

Inspection Photos  
Location Name: Shively #21-12  
Location ID: 320049



Photo #5 Well head.




Photo #6 stained soil under load off line from crude tank.