

Inspection Photos
Location Name: KAHN 33-15
API#: 05-071-07444
INSP. #: 695102979



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: KAHN 33-15
API#: 05-071-07444
INSP. #: 695102979



**PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.
CA DATE 10-15-20.**



**PHOTO 4: TRASH IN PIT. REMOVE ALL TRASH OR DEBREE IN
PIT COMPLY WITH RULE 603.f. CA DATE 10-15-20.**

Inspection Photos

Location Name: KAHN 33-15

API#: 05-071-07444

INSP. #: 695102979



PHOTO 5: TRASH IN PIT (OLD WIRE FROM PIT FENCE THAT HAS BEEN TAKEN DOWN). REMOVE ALL TRASH OR DEBREE IN PIT COMPLY WITH RULE 603.f. CA DATE 10-15-20.



PHOTO 6: AREA OF STAINED SOIL AROUND ENGINE SKID BETWEEN WELLHEAD AND ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.f.(2).D. CA DATE 7-22-20.