

Inspection Photos

Location Name: Wells Ranch USX AE 21-12

Location ID: 310627



Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign



Inspection Photos

Location Name: Wells Ranch USX AE 21-12

Location ID: 310627



Photo 3 – Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources