



39.80539, -109.0057, 5800.4ft, 204°  
07/16/2020 02:22:45 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Park Mountain 9026**

**API: 05-103-10000**

**Inspection: 700402442**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well.**

**Park Mountain 9026**

**API: 05-103-10000**

**Inspection: 700402442**





39.80503, -109.00611, 5850.6ft, 9°  
07/16/2020 02:24:53 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Separator & meter building.**

**Park Mountain 9026**

**API: 05-103-10000**

**Inspection: 700402442**



39.80524, -109.00588, 5848.2ft, 176°  
07/16/2020 02:24:08 PM





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Tank top 1.**

**Park Mountain 9026**

**API: 05-103-10000**

**Inspection: 700402442**





39.80464, -109.00462, 5818.4ft, 279°  
07/16/2020 02:36:48 PM





39.80497, -109.00556, 5842.9ft, 257°  
07/16/2020 02:32:20 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 7. Gage hatch 1.**

**Park Mountain 9026**

**API: 05-103-10000**

**Inspection: 700402442**





39.80489, -109.00544, 5833.3ft, 272°  
07/16/2020 02:31:43 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 8. Gage hatch 2.**

**Park Mountain 9026**

**API: 05-103-10000**

**Inspection: 700402442**



