

Inspection Photos
Location Name: WPF III-66N64W /18NWNE
Location #: 323559



Photo #1

WPF III A18-2 (05-123-13195) Wellsite
Temporarily Abandoned | TA



Photo #2

WPF III A18-2 Battery site
Inactive | Shut-down
Formerly served:
WPF III A 18-7, Carlson A18-17
Plugged & Abandoned | PA