

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2020

Submitted Date:

07/10/2020

Document Number:

699700171**FIELD INSPECTION FORM**Loc ID 335602 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

General Comment:

On July 9, 2020, COGCC Staff John Heil conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 335602 Federal 23-6-297 and Spill/Release ID 477183.

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: 7/7/2020 A corroded carbon steel bushing located within the pump house spilled/released produced water. The produced water traveled south over the facility lease road and pooled in a shallow depression. See Form 19 Doc #402439440 Spill/Release ID 477183 for more information. 7/9/2020 Erosion rills were present on the south side of the facility access road. Beyond the access road was an area with mud cracks where the spilled/released fluids appeared to have pooled. Potential impacted material (stained soil) was observed in the area where the fluids had pooled. A detectable hydrocarbon odor was present at time of inspection.

Corrective Action: Properly dispose of oily waste in accordance with 907.e.Date: 07/25/2020Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402441315	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5194162
699700173	20200709 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5194161