

Inspection Photos
Location Name: WPF III A-66N64W /18SWNE
Location #: 310589



Photo #1

Carlson A18-17 (05-123-32627) Wellsite

Plugged & Abandoned | PA

NOT cut / capped



Photo #2

WPF III A18-2 Battery site

Inactive | Shut-down

Formerly served:

WPF III A 18-7, Carlson A18-17

Plugged & Abandoned | PA

