

Inspection Photos
Location Name: Champlin (HER) 2-8
Location ID: 320245



Photo #1 Pump Jack.



Photo #2 Tanks.

Inspection Photos
Location Name: Champlin (HER) 2-8
Location ID: 320245



Photo #3 Meters, Separator & treater



Photo #4 pit

Inspection Photos
Location Name: Champlin (HER) 2-8
Location ID: 320245




Photo #5 stained soil in front of load off bucket.



Photo #6 Stained soil in back side of tanks.

Inspection Photos
Location Name: Champlin (HER) 2-8
Location ID: 320245



Photo #7 Stained soil north side of tanks.